



Herbert Birnbaum

PROOFING BASKETS

Made in Germany



Instructions for use of rattan proofing baskets



Spray the inside of the proofing basket slightly and evenly with water (e.g. with a water sprayer). Avoid development of big drops.



Use some rye flour and potato starch to dust the inside of the basket. Make sure that the whole surface is coated. To achieve this, spread the flour mixture in the basket with circular movements.



After 5 minutes, dust your basket again. Empty any surplus flour that is still in the basket after a short exposure time.



Result: you have created a thin and even flour layer. As of now, only dust as usual before every use.

Our cleaning instruction must be observed!